

# GAMAJET®

## LESS TIME CLEANING, MORE TIME HAULING

Need a reliable, durable, and effective way to clean your tanker, trailer or railcar? Gamajet's machines are not only designed to offer the most effective cleaning, they are also built to last twice as long as other tank cleaning machines before requiring service. They are also ergonomically-friendly, and they are backed by Gamajet's industry-leading service program.


To prevent cross contamination between loads or too much downtime, it is essential to have the right cleaning tool. Gamajet's patented rotary impingement machines have become a standard at truck washes for the past 45 years. Our fluid-driven machines spin and rotate in a precise, 360 degree indexing pattern, scouring 100 percent of the tanker or railcar. The impact and repeatable pattern of a Gamajet saves time, chemicals, energy, and money. Residual heels will be a thing of the past when you use a Gamajet. Backed by a 24-hour turnaround time on new orders, parts, and repairs, as well as unparalleled customer service, the Gamajet machines are the most effective and efficient rotary impingement machines on the market.

EFFICIENT 82% MORE

LESS 75% TIME

LESS 90% CHEMICALS

LESS 80% WATER



*Dry Bulk*



*Liquid Transport*



*Railcar Wash*

# GAMAJET IN THE TRANSPORTATION INDUSTRY



## TANK TYPES:

OTR Trailers	Liquid Bulk Trailers
Food Grade Trailers	Totes/IBCs
Railcars	ISO Containers
Dry Bulk	Vacuum Trucks

## RESIDUES:

Juice	Chemicals
Milk	Pharmaceuticals
Paint	Molasses
Petroleum/Oil	Syrups
Alcohol	and more...



*Pictured above is a Gamajet being lowered into position at a truck wash site.*


## SIDE BY SIDE COMPARISON

### Food Grade Tanker Cleaning Study

University of Florida's Research and Education Center conducted a test to evaluate the effectiveness of different tank cleaners for OTR (over-the-road) food grade tankers. Other cleaning methods such as spray balls and rotary wetting were not meeting FDA standards. Cleanliness testing was conducted by a series of swab analyses for various residues.

## RESULTS

Spray Ball: 43% Failed  
 Rotary Wetting: 69% Failed  
**GAMAJET IV: 100% PASSED**



**GAMAJET EZ-8**  
**CLEANING RANGE:** UP TO 75'  
**PRESSURE:** 50-300+ PSI  
**FLOW:** 40-120 GPM  
**IMPACT:** UP TO 30 LBS AT 25'

**GAMAJET IV**  
**CLEANING RANGE:** UP TO 100' RADIUS  
**PRESSURE:** 20-500+ PSI  
**FLOW:** 30-320+ GPM  
**IMPACT:** UP TO 100 LBS OF FORCE

[www.gamajet.com](http://www.gamajet.com)  
 1-877-GAMAJET | [sales@gamajet.com](mailto:sales@gamajet.com)  
 604 Jeffers Circle | Exton, PA 19341  
 Tel: (610) 408-9940 | Fax: (610) 408-9945

